

EPA Notification of Hazardous Waste SiteUnited States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

KSS 000 000 072
required

810609

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name S Oswalt Division; Butler Manufacturing CompanyStreet North Highway 83City Garden CityState KSZip Code 67846**B Site Location:**

Enter the common name (if known) and actual location of the site.

Name of Site S Oswalt Division; Butler Manufacturing CompanyStreet North Highway 83City Garden CityCounty FinneyState KSZip Code 67846**C Person to Contact:**

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title)

Overton, RobertPlant Manager

Phone

(316) 275-6101**D Dates of Waste Handling:**

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year)

1970

To (Year)

1980**E Waste Type: Choose the option you prefer to complete**

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item 1—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☐ Organics
- 2. ☐ Inorganics
- 3. ☒ Solvents
- 4. ☐ Pesticides
- 5. ☐ Heavy metals
- 6. ☐ Acids
- 7. ☐ Bases
- 8. ☐ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☐ Unknown
- 11. ☒ Other (Specify)

Paint Sludge**Source of Waste:**

Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper/Printing
- 6. ☐ Leather Tanning
- 7. ☐ Iron/Steel Foundry
- 8. ☐ Chemical, General
- 9. ☐ Plating/Polishing
- 10. ☐ Military/Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary/Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab/Hospital
- 17. ☐ Unknown
- 18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

F0 17

Form Approved
GSA No. 2000 0138

EPA-ARHM/HAZM

JUN 11 1981

Region VII K.C.

Notification of Hazardous Waste Site	Side Two	
F Waste Quantity Place an X in the appropriate boxes to indicate the facility types found at the site. In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons. In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.	Facility Type 1. <input type="checkbox"/> Piles 2. <input type="checkbox"/> Land Treatment 3. <input type="checkbox"/> Landfill 4. <input type="checkbox"/> Tanks 5. <input type="checkbox"/> Impoundment 6. <input type="checkbox"/> Underground Injection 7. <input type="checkbox"/> Drums, Above Ground 8. <input type="checkbox"/> Drums, Below Ground 9. <input checked="" type="checkbox"/> Other (Specify) <u>Disposal on soil top surface.</u>	Total Facility Waste Amount cubic feet _____ gallons _____ Total Facility Area square feet <u>5,000</u> acres _____

G Known, Suspected or Likely Releases to the Environment:
Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☒ Likely ☐ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

No map

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Sludge from paint booth was dumped on the ground during approximate period from 1970-1980. The solvent evaporated leaving solidified pigment which currently gives a color indication. Disposal site is at the address indicated which is not near water or housing.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name Ben F. Ervin
Street P. O. Box 917
City Kansas City State MO Zip Code 64141
Signature Ben F. Ervin Date 6/9/81

☒ Owner, Present
☐ Owner, Past
☐ Transporter-
☐ Operator, Present
☐ Operator, Past
☐ Other



Butler Manufacturing Company
BMA Tower, Penn Valley Park,
Kansas City, Missouri 64141
Phone: (816) 968-3000

June 9, 1981

U.S. EPA Region 7
Sites Notification
Kansas City, Missouri 64106

Gentlemen:

Attached is notification which indicates a discontinued practice of dumping paint sludge on our property located at Garden City, Kansas.

Cordially yours,

A handwritten signature in blue ink, appearing to read "Ben F. Ervin".

Ben F. Ervin
Corporate Safety Engineer

BFE:ns

EPA-ARHM/HAZM

JUN 11 1981

Region VII K.C.



POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION

SITE NUMBER

7

KS000010089

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME

Oswalt Div.; Butler Mfg Co

B. STREET (or other identifier)

North Hwy 83

C. CITY

Garden City

D. STATE

KS

E. ZIP CODE

67846

F. COUNTY NAME

Finney

G. OWNER/OPERATOR (if known)

1. NAME

Ben F. Ervin
P.O. Box 917Kansas City, MO 64141
Contact: Robert Overton
Plant Mgr.

2. TELEPHONE NUMBER

316-275-6101

H. TYPE OF OWNERSHIP (if known)

☐ 1. FEDERAL☐ 2. STATE☐ 3. COUNTY☐ 4. MUNICIPAL☒ 5. PRIVATE☐ 6. UNKNOWN

I. SITE DESCRIPTION

5000 sq. ft. facility, operated from 1970 to 1980.
Indicated disposal site not located near water
or housing.

J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.)

Superfund Notification

K. DATE IDENTIFIED
(mo., day, & yr.)

6/81

L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM

Wastes reported: solvents, paint sludge, F017.
Sludge from paint booth was dumped on ground during
approx. period 1970-1980. Solvent evaporated
leaving solidified pigment which currently
gives a color indication. @
Reported likely release to environment.

M. PREPARER INFORMATION

1. NAME

Joy Haff

2. TELEPHONE NUMBER

374-6531

3. DATE (mo., day, & yr.)

7/4/81